JH/OS Rescue workers set about removing the jagged remnants of the coach in which ten people lost their lives at Irk Valley Viaduct near Manchester.

Leading coach of the 7.20 a.m. Bury-to-Manchester train train drepped a distance of eighty feet from the scene of the crash way above. The accident occurred when the electric train was in head-on collision with a steam train from Manchester to Bacup. Mercifully the coupling on the leading coach snapped, otherwise the rest would NAME have followed with a certain increase in the death roll.

Manchester

102420-6

MATCHESTER TRAIN CRASH.

Rescue workers set about removing the jagged remnants of the coach in which ten people lost their lives at Irk Valley Viaduet near Manchester. The leading coach of the 7.20 a.m. Bury-to-Manchester train dropped a distance of eighty feet from the scene of the crash way above. The accident occurred when the electric train was in head-on collision with a steam train from Manchester to Basup. Mercifully the coupling on the leading coach snapped, otherwise the rest would have followed with a certain increase in the death roll.