

KARIBA: WEED MAKES DAM PROBLEM

ZERO IN THE GATE TITLE ENDS AT 31

CAMERA: LIBRARY: FISHER

1.	G.V.	ELEVATED THE KARIBA DAM	34.L
2.	G.V.	PAN. ALONG THE DAM TO WHERE WORK IS IN PROGRESS AT ONE END	42 F
3.	G.V.	MEN WORKING	46.
4.	S.V.	DITTO	50
5.	L.V.	CRANE WORKING OVER THE EDGE OF THE DAM	55.
6.	S.V.	THE CRANE DRIVER WORKING	59.
7.	L.V.	PAN. AS THE CRANE LETS ITS LOAD DOWN INTO A LORRY	64.
8.	L.V.	TRAFFIC MOVING ACROSS THE TOP OF THE DAM	71.
9.	L.V.	CRANE LIFTING A LOAD UP FROM BESIDE THE DAM	76 <sup>1</sup> / <sub>2</sub>
10.	G.V.	THE DAM PAN TO A G.V. OF THE LAKE	83.
11.	L.V.	PAN. ACROSS THE LAKE SHOWING VAST PATCHES OF WEED	89.
12.	L.V.	PAN. THE WEED	96.
13.	S.V.	COLOURED MAN HOLDING A BUNDLE OF THE WEED	100.
14.	C.U.	THE WEED	106.
15.	G.V.	TWO MEN ON A RAFT MAKING THEIR WAY THROUGH ONE OF THE WEED PATCHES <del>XXXXX</del>	110.
16.	L.V.	DITTO	113.
17.	S.V.	DITTO	118.
18.	G.V.	OF THE LAKE SHOWING THE WEED PATCHES	126.

LENGTH WITH TITLE 102ft

KARIBA ✓ 1-18.  
 INST-DAMS, DYKES 1-18  
 R