

C.L. Edwards, 16mm via Rucker,
16 mm via Farquharson
BRIDGE COLLAPSE
Tacoma, Washington

1. Still picture of bridge before collapse.
2. Gen. v. wrecked bridge.
3. Closeup sign Tacoma Narrows Bridge.
4. Gen. v. engineers on bridge.
5. Semi-v. engineers inspect broken cable.
6. Closeup view engineers inspect broken cable.
7. Inspect steel wall broken away from cement.
8. Closeup steel wall broken away from cement.
9. Crack in cement.
10. Closeup crack in cement.
11. Pan of leaning tower.
12. People watch.
13. Closeup of same.
14. Cable swings.
15. Crack in wall.
16. Gen. v. steel plates on side of bridge.
17. Closeup of steel plates.
18. Under part of bridge, steel plates swinging.
19. Gen. v. Farquharson tests model.
20. Semi-v. of same.
21. Meter registers motion of swaying.
22. How girder with holes in side inspected.
23. Side v. of same.
24. Man surveying bridge.
25. Gen. v. bridge swinging during test.
26. People walking on bridge as it is swinging.
27. ~~xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx~~ Car on bridge during swaying.
28. Roadway of bridge during swaying.
29. Rails rock -- cars pass each other on bridge.
30. Long view bridge swings.
31. Side-v. of same.
32. Side-v. lights on bridge swinging.
33. Gen. v. bridge collapses actual crash.
34. Gen. v. bridge collapse.
35. " " " "
36. Long v. of bridge from water after collapse.
(see next page #2)

BRIDGE COLLAPSE

Tacoma, Washington

- 37. Tug under bridge which was almost hit.
- 38. Coast Guard under bridge on which wreckage was found aboard.
- 39. Wires dangling from bridge.
- 40. Pan broken pieces of bridge to wreckage dangling in water.
- 41. Long view bridge and people in foreground.
Toll gate with sign reading "Closed".

Tacoma Bridge Collapses

0252520

	Title	
1	GV Wrecked bridge	7
2	LV Sign "Tacoma Narrows Bridge"	4
3	GV Engineers on bridge	4
4	LV Engineers inspect broken cable	4
5	CU Ditto	5
6	CU Steel wall broken away from concrete	4
7	CU Track	4
8	LV Pan wrecked bridge	7
9	Front View: Bridge swaying	6
10	LV Steel plates on side of bridge	4
11	CU Ditto	5
12	LV Farquarhsen testing model	5
13	SV Ditto	5
14	SV Reading meters	4
15	SV Surveyor	4
16	FV Bridge swaying; traffic going over	9
17	TV Ditto	7
18	CU Car going over swaying bridge	7
19	LV Showing railings swaying up and down	10
20	SV Bridge swaying	10
21	GV People watching	3
22	SV Ditto	3
23	GV Bridge swaying	8
24	LV Ditto	7
25	GV Bridge swaying collapses	23
	BRIDGE COLLAPSES	
26	GV From river: wrecked bridge	11
27	LV Wrecked bridge	5
28	SV Wires dangling from bridge	5
29	SCU Ditto pan to wreckage dangling in water	5
30	FV Road closed to traffic	5
31	GV Wrecked bridge	5

Handwritten signature

Blue. Check National Sound. by Blue

(Length with title 199 Ft)