

ROYAL SCOT TRAIN CRASHES IN SCOTLAND.

1.	G.V.	Wreck of Royal Scot at Abington, Scotland. (First 7 feet for super)	
2.	L.V.	Ditto	
3.	L.V.	Cranes lifting coach. Wreckage and men in f.g.	5
4.	M.V.	Coach being lifted	4
5.	S.V.	Wrecked coach on side	4
6.	L.V.	Rail bent by heat of sun ????????????????	4
7.	S.V.	Ditto	3 20
8.	L.V.	Bent rail at side of track pan across to men repairing track	7
9.	E.V.	Men working on track	3 30
10.	S.V.	Man working on track	2
11.	S.V.	Ditto	3
12.	SCU.	Man using spanner pan down to spanner	3 38
13.	S.V.	Man looking at safety coupling	7
14.	C.U.	Safety Coupling	3 10
15.	S.V.	Men working on safety coupling	4 14
16.	L.V.	Coach (STEEL) with wrecked door	4 18
17.	C.U.	Wrecked door of coach	4 22
18.	S.V.	Ditto	4 26
19.	L.V.	Wreckage	4 30
20.	S.V.	Coach on side crushing wall by side of track	5 38

TOTAL LENGTH WITH TITLE

82

British Journal

£ 750 90 x
ready service.