

5151  
2915

2-829F01

PATHE NEWS 57/93

RAILWAY MODERNIZATION - BRIDGE

DEMOLISHED AND VIADUCT INSPECTION UNIT.

CAMERAMAN

GODDARD  
WHITAKER *NOG*

ZERO IN GATE TITLE ENDS AT 30

- 1 L.V. PAN SHOT EXPRESS TRAIN TRAVELLING FAST AWAY INTO BACK VIEW 37 G
- 2 G.V. ELEVATED SHOT SHOWING EXCAVATIONS FOR LAYING FURTHER TRACKS ALONGSIDE EXISTING ONES 41 G
- 3 L.V. TRAIN PASSING OVER BRIDGE AS DOWN BELOW WORKMEN ARE ~~XXXXXXXX~~ CARRYING OUT WIDENING OPERATIONS 49 G
- 4 G.V. THE BRIDGE WHICH IS TO BE DEMOLISHED 54 G
- 5 S.V. WORKMEN ON TOP OF THE BRIDGE DRILLING HOLES FOR THE CHARGES 59 G
- 6 S.C.U. DITTO 63 G
- 7 S.V. THE LAST TRAIN PASSES UNDER THE OLD BRIDGE BEFORE IT IS DEMOLISHED 70 G
- 8 S.V. WORKMEN CARRYING PLANKS TO PLACE BETWEEN THE LINES WHEN THE BRIDGE IS BLOWN UP TO PREVENT THE RAILS FROM BEING DAMAGED 74 G
- 9 L.V. ELEVATED SHOT DITTO 78 G
- 10 S.C.U. CHARGE BEING PUSHED INTO HOLE 82 G
- 11 L.V. THE BRIDGE AT NIGHT TIME WITH SAND BAGS ON TOP ABOUT TO BE DEMOLISHED 88 G
- 12 S.V. WORKMEN SHOUTING WARNING AS HE IS ABOUT TO DETONATE THE BRIDGE. HE IS UNDER COVER OF A SAND BAG SURROUND 90 G
- 13 C.U. THE WORKMEN AT 91 TURNS A SWITCH TO BLOW UP THE BRIDGE 91 G
- 14 L.V. THE BRIDGE AS AT 92 IT IS BLOW TO SMITHERENS, THE DUST CLEARS AT 102 AND WE CAN SEE THE RUBBLE LYING ON THE TRACK 111 G
- 15 S.V. WORKMEN CLEARING THE RUBBLE FROM THE LINES AND THROWING IT INTO EXCAVATOR BUCKETS 117 G
- 16 A.S. WORKMEN CLEARING RUBBLE 123 G
- 17 C.U. EXCAVATOR BUCKET CLEARING THE RUBBLE 128 G
- 18 L.V. FIRST TRAIN PASSING THE SIGHT OF THE DEMOLISHED BRIDGE 135 G

VIADUCT INSPECTION UNIT

- 19 G.V. SLIP PAN TO SHOT OF KNARESBOROUGH VIADUCT 140 W
- 20 S.V. DIESEL ENGINE LEAVING STATION AND TOWING THE VIADUCT INSPECTION UNIT OUT ONTO THE VIADUCT 144 W
- 21 S.V. PAN SHOT THE INSPECTION UNIT BEING TOWED OUT 159 W
- 22 S.C.U. TWO MEN WHO ARE DEALING WITH THE INSPECTION 162 W
- 23 L.V. ELEVATED SHOT THE INSPECTION UNIT ON THE VIADUCT 166 W
- 24 C.U. WORKMEN 168 W
- 25 S.V. THE INSPECTION UNIT SWINGING OUT OVER THE EDGE OF THE VIADUCT 172 W
- 26 S.V. ELEVATED SHOT MEN GOING DOWN ON INSPECTION PLATFORM 178 W

2-279401

RAILWAYS CONTD.

27	A.S.	THE HUGE ARM LOWERING THE PLATFORM AND MANOEVERING BENEATH THE VIADUCT	183 W
28	C.U.	UNDERNEATH THE ARCH	187 W
29	L.V.	THE UNIT HANGING OVER THE EDGE OF THE VIADUCT	192 W
30	A.S.	THE INSPECTION PLATFORM WITH THE MEN ON IT COMING OUT FROM UNDERNEATH THE ARCH	198 W
31	C.U.	ONE OF THE MEN SCRAPING AT THE VIADUCT'S SURFACE AND TALKING ON TELEPHONES TO THE TEAM OF MEN ABOVE	203 W
32	L.V.	THE ARM JOINING OF THE INSPECTION UNIT AND AT 206 CAMERA PANS DOWN TO SHOW HOUSES AND ROAD SOME DISTANCE BELOW	210 W
33	C.U.	MAN OPERATING CONTROLS BY WHICH WE CAN MANOEUVRE THE INSPECTION PLATFORM WHILE HE IS ON IT	213 W
34	L.V.	THE INSPECTION UNIT HANGING OVER THE VIADUCT	220 W

LENGTH WITH TITLE 196

RAILWAYS, Kent - 1-34  
 KNAREBOROUGH - 1-34  
 TRANS-RAILWAYS - BRITISH  
 1-34.  
 BUILDINGS - BRIDGES 1-18.  
 IND - DETONATING 1-18.

TITLES " "

V.B.