

2-018521

(7).

TITLE.:- MAKING ENDS MEET.

Picture.:- The other half can be seen in the distance.
Both --

--parts have been made watertight, to allow them to be towed
to dock for unloading --

--her cargo of eight-thousand tons of coal, which she
was conveying --

--to Italy when misfortune overtook her on the sandbanks
off Dungeness.

For a while she lay helpless, and then, her back broke.
Here is the breach as it appears -

--now that the two halves have been placed in position for
connecting-up --

--into a whole vessel again. It won't take long when
these clever people, who practice "ship-surgery" --

--get to work on her. Here's what she'll look
like when the job's finished.